REVISED 4/2/03



LOOP DETECTOR IN SHOULDER SECTION

NOT TO SCALE