


# HORIZONTAL SIGNAL MOUNTING

NOT TO SCALE

4/1/98

REVISED