

QUADRUPLE LOOP INSTALLATION

NOT TO SCALE

4/1/98

REVISED