

PARALLEL HYDRANT ASSEMBLY

NOT TO SCALE

10/01/00

REVISED