REVISED 4/1/98



PERPENDICULAR HYDRANT ASSEMBLY

NOT TO SCALE