


# FLEXIBLE PIPE TO MANHOLE JOINT

NOT TO SCALE

3/1/06

REVISED