REVISED 3/1/06



HYDRANT ASSEMBLY-PERPENDICULAR

NOT TO SCALE