

MANHOLE JOINT

NOT TO SCALE

3/1/06

REVISED