


4/2/03

REVISED



LOOP DETECTOR IN SHOULDER SECTION

NOT TO SCALE